

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3529	DATE	March, 26, 2015
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	The circlips of turning clutch are not durable enough. They may be broken after certain hours operation. That leads to deteriorate of the turning performance.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDN-C425	「ER467」	2008～2014	2,016
	「ER456」	2008～2014	1,563
		TOTAL	3,579