

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2165	DATE	March 25, 2015
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to improper surface finish quality of variable valve timing unit, some installation bolts become loose. As a result, valve timing control unit becomes broken; in the worst case, vehicle turns out as breakdown condition and not possible to restart.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-AUCJZ	「VW Golf 1.2/77kW」	MY2014-MY2015	4,993
	「VW Golf Variant 1.2/77kW」	MY2014-MY2015	3,200
DBA-6RCJZ	「VW Polo 1.2/66kW」	MY2015	7,445
DBA-6RCJZW	「VW Cross Polo 1.2/66kW」	MY2015	319
		Total	15,957