

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2163	DATE	March 25, 2015
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to improper manufacturing of Head rest assembling, guide rods from other production model may be installed on front driver and front passenger seat. As a result, some head rests can be pulled out of seats completely without unlock; which condition does not fulfill Japanese Safety Regulation Article 22.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-7NCTH	「VW Sharan 1.4 110kW」	MY2014	27
		Total	27