

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2160	DATE	March 25, 2015
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	<p>Due to a combination of production tolerance issues and vehicle vibration during dynamic driving, it is possible that, in rare cases, a fuel leak may occur in the vehicle's fuel injection system. Leaking fuel, in the presence of an ignition source, may result in a fire.</p> <p>Additionally, some vehicles may benefit from having the thermostat replacement.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-4FCAJA	A6 Avant	2011	2
ABA-4GCGWC	A7 SB 3.0Tq	2011 - 2012	474
ABA-4GCGWS	A6 3.0Tq		187
ABA-4HCGWF	A8 3.0Tq		56
ABA-4LCJTL	Q7 3.0Tq		88
ABA-4LCJTS			370
ABA-8FCAKF	S5 Cabriole	2011	11
ABA-8FCGWF		2012	10
ABA-8KCAKF	S4/S4 Avant	2011 - 2012	216
ABA-8KCGWF		2013	37
ABA-8TCGWF	S5	2012	15
ABA-8TCGWL	S5 SB		45
DBA-4GCGWC	A7 SB3.0Tq		238
DBA-4GCGWS	A6 3.0Tq / A6 Avant 3.0Tq		133
DBA-4HCGWF	A8 3.0Tq		62
		Total	1,944