

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3527	DATE	19 March 2015
MANUFACTURE	HITACHI CONSTRUCTION MACHINERY CO. , LTD		
DESCRIPTION OF DEFECT	The packing of unused oil filler cap on top of engine will deteriorate by muffler heat, and then there is possibility that the oil filler cap will loosen. If it is used continually as this condition, the oil filler cap may drop. In this case, there is possibility that the engine oil will leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SD-HS56	「ZW220」	2005 - 2006	15
JDS-HS56		2007 - 2013	108
JDS-HS57	「ZW250」	2007 - 2013	16
SD-S56	「ZW220」	2005 - 2007	22
JDS-S56		2007 - 2010	53
SD-S57	「ZW250」	2006	5
JDS-S57		2007 - 2010	16
		TOTAL	235