

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2166	DATE	March 25, 2015
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to improper repair finish of fuel distributor end by the low temperature welding process, welding spot may start leaking fuel.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-16CPL	「VW The Beetle 2.0T」	MY2014-MY2015	76
		Total	76