

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3560	DATE	April 21. 2015
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Regarding the rear suspension, the piston and the piston shaft may be undertightened with nuts owing to faults in the nut tightening process. Continued use in such a condition can cause the nuts to fall out, whereby shock-absorbing function could be lowered and running stability could be significantly impaired.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-SC59	CBR1000RR	2014~2015	230
		2015	110
		TOTAL	340