

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3542	DATE	April 16,2015
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Due to inappropriate manufacturing process for the element in the electric water heater which controls the temperature, the element may be cracked by the repeated use of the electric water heater. As a result, the driver may not be able to keep the eyesight safely when the window shield is misted due to the declined heating performance caused by the unstable heater control.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-HA3W	「i-MiEV」	2009～2010	807
		2009～2010	807