

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3554	DATE	April 14, 2015
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Regarding the front forks, the bush holder may be inadequately chamfered on its edge and the pivot arm bush may be inadequately surface-treated, whereby grease between the bush holder and the bush may flow out, increasing the frictional resistance between the front pivot arm and the side face of the bush. If the vehicle continues in service in such a condition, the right front pivot arm can be excessively stressed and eventually broken. In the very worst case, the front brake cable could be pulled when the front brake is applied, whereby the front wheel would be locked, causing the vehicle to fall over or rendering it disabled.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JBH-TD02	GYRO X	2011~2013	7,803
		2011~2013	210
		2012~2013	132
		TOTAL	8,145

THOSE DELIVERED AS “REPLACEMENT/SERVICE PARTS”

PARTS	PART NO.	DELIVERED AS “SERVICE PARTS”	NUMBER OF PARTS
FRONT FORK ASSEMBLY	51110-GFY-630	2011~2015	3,932
	51110-GFY-660		
	51110-GM6-316		
	51110-GG2-316		
PIVOT ARM BUSH	51314-GFY-661	2012~2015	4,027
	51314-GM6-000		
	51314-GG2-900		
		TOTAL	7,959