

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3543	DATE	April 3 ,2015
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		Due to an inadequate installation instruction, some of the light-duty trucks have steering gear boxes for a larger steering angle. For this reason, if the truck is stopped suddenly with the steering wheels turned to the maximum angle, the tires might come in contact with other parts.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TPG-NKR85AN TPG-NKR85AR TRG-NKR85AR	[ELF]	2014-2015	126
TPG-NMR85AN TPG-NMR85AR TRG-NMR85AN TRG-NMR85AR		2014-2015	43
		TOTAL	169