

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3 5 4 4	DATE	Apr 1,2015
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	<p>Due to poor routing of the engine's electronic control wiring on wheel crane motors, there are cases where the wiring may be damaged by the engine's vibrations.</p> <p>As a result, with continued use in this condition, there is a risk of the wires short circuiting, causing the motor to stop.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UDS-T008	TADANO 「GR-700N-1」	2013-2015	390
UDS-EG04	KOBELCO 「RK700-2」	2015	1
		TOTAL	391