

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3556	DATE	April 16, 2015
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	The spring that fixes the high beam headlight bulb interferes with the back cover of the bulb when assembling the cover after the bulb due to the spring shape being improper. Since the bulb cannot be fixed normally, radiation direction of the high beam headlight can have probable unconformity with article 32 of the safety regulation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-DA17W	EVERY	2015	779
ABA-DR17W	NV100 CLIPPER RIO		1
ABA-DG17W	SCRUM		61
		TOTAL	841