

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3582	DATE	May.28. 2015
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As regards certain passenger's airbag inflators, the container of the inflator could break and scatter the inflator component parts around, causing injury to the vehicle occupant in the event of the airbag deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GE6	「FIT」	2008	147,115
DBA-GE7			12,578
DBA-GE8			21,952
DBA-GE9			2,189
DBA-GB3	「FREED」		52,899
DBA-GB4			5,584
DBA-RE3	「CR-V」		3,125
DBA-RE4			3,159
DBA-GB1	「MOBILIO」		1,303
DBA-GB2			253
DBA-GK1	「MOBILIO SPIKE」		4,894
DBA-GK2			897
ABA-CL7	「ACCORD」		241
ABA-CL8			92
ABA-CL9			253
DBA-CL7			910
DAA-ZE2	「INSIGHT」	37	
		TOTAL	257,481