

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3580	DATE	May 22, 2015
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On inflators installed in frontal driver frontal air bag modules, as part of the parts supplier's continuing investigation of returned parts from fields, excessive internal pressure of the inflator case, which may potentially lead to rupture, was found. Therefore, although the root cause has not been identified, inflators of the same type which had been manufactured till a certain period are replaced with the new ones for preventive measures.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TC-SK82V	Mazda 「BONGO」	2004-2006	6831
TC-SK82M		2004-2006	1552
KQ-SKF2V KR-SKF2V		2004-2006	3067
KR-SKF2M		2004-2006	1197
TC-SK82T		2004-2006	9894
TC-SK82L		2004-2006	1260
KQ-SKF2T KR-SKF2T		2004-2006	3332
KR-SKF2L		2004-2006	813
KR-SKF6V	Mazda 「BONGO BRAUNY」	2004-2006	1483
KR-SKF6M		2004-2006	519
KR-SKFHV		2004-2006	30
KR-SKFHM		2004-2006	17
TC-SKE6V		2004-2006	1450

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KG-SY54T	Mazda 「TITAN」	2004	78
KG-SY54L		2004	35
KG-SY56T		2004	209
KG-SY56L		2004	114
TC-SYE4T		2004-2006	1364
TC-SYE6T		2004-2006	6262
KR-SYF4T		2004-2006	520
KR-SYF4L		2004-2006	87
KR-SYF6T		2004-2006	2672
KR-SYF6L		2004-2006	365
DBA-GG3P	Mazda 「ATENZA」	2005-2006	1290
DBA-GG3S		2005-2006	2886
DBA-GY3W CBA-GY3W		2005-2006	3490
DBA-GGEP		2005-2006	954
DBA-GGES		2005-2006	510
DBA-GYEW		2005-2006	845
TC-SK82VN	Nissan 「BANETTE」	2004-2006	22239
TC-SK82MN		2004-2006	4523
KQ-SKF2VN KR-SKF2VN		2004-2006	1356
KR-SKF2MN		2004-2006	658

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TC-SK82TN	Nissan 「BANETTE」	2004-2006	13473
TC-SK82LN		2004-2006	1859
KQ-SKF2TN KR-SKF2TN		2004-2006	532
KR-SKF2LN		2004-2006	164
TC-SK82VM	MITSUBISHI 「DELICA」	2004-2006	1835
TC-SK82MM		2004-2006	287
KQ-SKF2VM KR-SKF2VM		2004-2006	630
KR-SKF2MM		2004-2006	339
KR-SKF6VM		2004-2006	253
KR-SKF6MM		2004-2006	182
TC-SKE6VM		2004-2006	572
TC-SK82TM		2004-2006	1613
TC-SK82LM		2004-2006	188
KQ-SKF2TM KR-SKF2TM		2004-2006	436
KR-SKF2LM		2004-2006	122
			Total