

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3579	DATE	May 22, 2015
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On inflators installed in frontal passenger air bag modules, as part of the parts supplier's continuing investigation of returned parts from fields, density deterioration of the gas generator, which may potentially lead to rupture, was found. Therefore, although the root cause has not been identified, inflators of the same type which had been manufactured till a certain period are replaced with the new ones for preventive measures.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GG3P	Mazda 「ATENZA」	2005-2007	2178
DBA-GG3S		2005-2007	5029
DBA-GY3W CBA-GY3W		2005-2007	5689
DBA-GGEP		2005-2007	1805
DBA-GGES		2005-2007	933
DBA-GYEW		2005-2007	1520
		Total	17154