

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3578	DATE	May 22, 2015
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	Regarding passenger airbag inflator, as the result of investigation of collected parts from the field by parts supplier, there were some cases which insufficient air sealing on inflator body were confirmed. Therefore, although the cause is still unknown, as the airbag may not deploy properly when it deploys, the inflator will be replaced with new one as preventive measures.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LA-GD2	「IMPREZA」	2004~2007	7,091
LA-GD3		2004~2007	3,862
TA-GDA		2004~2007	5,933
GH-GDB		2004~2007	14,438
DBA-GDC		2006~2007	368
DBA-GDD		2006~2007	234
LA-GG2		2004~2007	34,726
LA-GG3 TA-GG3		2004~2007	17,942
TA-GG9		2004	145
TA-GGA		2004~2007	2,821
DBA-GGC		2006~2007	2,317
DBA-GGD		2006~2007	1,274
		TOTAL	91,151