

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3562	DATE	15 May, 2015
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO., LTD.		
DESCRIPTION OF DEFECT	<p>In the water pump's engines for the water sprinkler trucks, due to an irrelevant cam's figure, there is a possibility of the engine rotating in reverse if it is suddenly placed at its max RPM just before it would normally be shut down.</p> <p>Therefore, the element inside the air cleaner and the air cleaner cover involve the risk of being damaged by fire due to hot exhaust gasses being sent back into engine's intake.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-XZU600M	HINO DUTRO	2011,2012	16
SKG-XZC605M		2012	4
SDG-XZU700X		2011,2012	46
TKG-XZU600M		2012,2013,2014	57
TKG-XZU605M		2013,2014	102
TKG-XZU700X		2012,2013,2014,2015	347
BDG-XZU304E		2014	1
SKG-FC9JCAP	HINO RANGER	2012	4
SKG-FC9JDAA		2012	1
SDG-FC9JCAP		2013	1
SDG-FC9JDAP		2013	1
KC-FC3JCBD		2012	1
KC-FC2JCBD		2012	1
TKG-FC9JCAA		2015	1
TKG-FC9JCAP		2013,2014,2015	8
PB-FC6JCFA		2013	1
KK-FC3JCEA		2013	1
KK-FC3JCDA		2014	1
ADG-FC6JCWA		2013	2
TKG-XZU605	TOYOTA DYNA	2014	11

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PDG-NPR75N	ELF	2008	1
PKG-NPR75N		2009	1
SKG-NPR85YN		2011,2012,2013,2014	473
SKG-NKR85AN		2013	1
TKG-NKR85AN		2012,2013,2014	7
TKG-NPR85YN		2015	31
TKG-NJR85AN		2012,2013,2014	5
TPG-NJR85AN		2015	1
TPG-NPR85YN		2015	2
PB-NRR35C3	FORWARD JUSTON	2012	1
PB-FRR35C3S	FORWARD	2012	1
KK-FRR35C3S		2012	1
KK-FRR35C4S		2014	1
ADG-FRR90C3S		2012,2014	12
PKG-FRR90S1		2012,2014	4
PKG-FRR90S2		2014	2
SKG-FSR90S2		2012	1
SKG-FRR90S1		2012	9
TKG-FRR90S1		2013,2014,2015	57
PDG-FE83DY	FUSO CANTER	2009	1
SKG-FEB90		2011	1
SKG-FEA50		2012	1
TKG-FEB90		2012,2013,2015	11
KK-FH21GC	FUSO FIGHTER	2012	3
KK-FH21GE		2013	1
KK-FK71HC		2012	2
KK-FK71GC		2013	1
PA-FK71D		2012,2013,2014	9
PA-FK71DC		2012,2013	3
TKG-FK71F		2013	1
PDG-FK71R		2014	2
QKG-FU50VY	FUSO SUPER GREAT	2014	1
SKG-MK38L	CONDOR	2012	1
KK-MK21A		2012	4
TKG-MK38L		2014,2015	3
		TOTAL	1263

【NOTICE】

•From the above range of model year recalled, there is possibility that not target products are included.

SELLING AS THE REPAIR PARTS FOR REPLACING

PRODUCT NAME	TYPE	MODEL NUMBER AND MODEL YEAR	NUMBER	OTHER
WATER PUMP'S ENGINE	L70	M22688 ~ M48533 2011,2012,2013, 2014,2015	15	BUILD TYPE LH02-30R LH02-301R LH03-301R LH04-30R LH04-301R LH04-302R LH05-30R
		TOTAL	15	

【NOTICE】

- The vehicle using the repair parts for replacing is carried out same remediation as the recall.
- From the above range of model number, not voluntary remediation's products are included.