

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2175	DATE	May.14. 2015
MANUFACTURER	HONDA OF AMERICA MFG., INC.		
DESCRIPTION OF DEFECT	Some of the inflators of the passenger's airbags withdrawn from the market showed low gas generating propellant density which could have caused unusual airbag deployment. Although the cause is not determined yet, inflators of the same type manufactured during a certain period of time will be replaced with new ones by way of precautionary measures.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GD6	「FIT ARIA」	2004~2005	1,819
		2005	948
DBA-GD7		2004~2005	408
		2005	174
DBA-GD8		2004~2005	2,974
		2005	1,519
		2005~2006	4,140
		2006~2007	2,129
		2007	2,053
DBA-GD9		2004~2005	1,117
	2005	383	
	2005~2006	1,125	
	2006~2007	738	
	2007	436	
		TOTAL	19,963