

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	GAI-2174	DATE	May.14. 2015
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Some of the inflators of the passenger's airbags withdrawn from the market showed low gas generating propellant density which could have caused unusual airbag deployment. Although the cause is not determined yet, inflators of the same type manufactured during a certain period of time will be replaced with new ones by way of precautionary measures.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-YH2	「ELEMENT」	2004	119
		2005	120
DFA-EN2	「CIVIC GX」	2004	112
		TOTAL	351