

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2173	DATE	May.14. 2015
MANUFACTURER	HONDA AUTOMOBILE (THAILAND) CO., LTD.		
DESCRIPTION OF DEFECT	Some of the inflators of the driver's SRS airbags withdrawn from the market showed abnormal output of the inflator internal pressure which could have caused unusual airbag deployment. Although the cause is not determined yet, inflators of the same type manufactured during a certain period of time will be replaced with new ones by way of precautionary measures.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GD6	「FIT ARIA」	2004~2005	478
		2005	945
DBA-GD7		2004~2005	146
		2005	174
DBA-GD8		2004~2005	920
		2005	1,514
		2005~2006	4,135
		2006	799
DBA-GD9		2004~2005	580
		2005	381
	2005~2006	1,124	
	2006	260	
		TOTAL	11,456