

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2168	DATE	May 11 <sup>th</sup> , 2015
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	On the transmission, the design of the actuator which locks the parking gear is inappropriate. Thus, even operating the gear selector switch, it does not shift to P-range and parking gear will not be locked. Or, the parking gear cannot be deactivated and the vehicle cannot be started from P-range.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-1Z00	BMW i3	2013 - 2014	242
DLA-1Z06		2013 - 2014	328
		TOTAL	570