

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3592	DATE	June.25.2015
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the single-stage front passenger frontal airbag inflator, while the root cause has not been identified, there is a possibility that the inflator could rupture during the deployment of the airbag; therefore, for all affected vehicles, the airbag will be replaced with a new one as a precautionary measure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ANH10W	[ALPHARD G] [ALPHARD V]	2007-2008	25,430
DBA-ANH15W		2007-2008	3,730
TA-MNH10W CBA-MNH10W		2007-2008	8,083
TA-MNH15W CBA-MNH15W		2007-2008	2,711
DAA-ATH10W	[ALPHARD HYBRID]	2007-2008	3,060
DBA-ACM21W	[IPSUM]	2007-2008	3,939
DBA-ACM26W		2007-2008	863
DBA-AZR60G	[NOAH] [VOXY]	2007	12,531
DBA-AZR65G		2007	2,239
TA-JCG10	[BREVIS]	2007	190
TA-JCG11		2007	49
TA-JCG15		2007	20

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBE-NCP50V	[PROBOX]	2007-2008	10,403
DFE-NCP52V		2007-2008	159
CBE-NCP51V	[PROBOX] [SUCCEED]	2007-2008	28,816
CBE-NCP55V		2007-2008	10,707
CBA-NCP58G		2007-2008	8,379
CBA-NCP59G		2007-2008	2,407
KP-NLP51V		2007	971
TA-GX110W		2007	234
TA-GX115W	[MARK II BLIT]	2007	38
TA-JZX110W		2007	82
TA-JZX115W		2007	24
DBA-KSP90		2007-2008	57,962
DBA-NCP91	[VITZ]	2007-2008	13,320
CBA-NCP95		2007-2008	16,150
DBA-SCP90		2007-2008	76,712
DBA-KSP92		2007-2008	5,439
CBA-NCP96	[BELTA]	2007-2008	2,792
DBA-SCP92		2007-2008	14,247
	TOTAL		311,687