

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3588	DATE	June 25,2015
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In the particular inflators for the passenger airbags, the body of the inflator may rupture during its deployment causing the component parts of the inflator to be flown apart resulting in the injury to the passengers.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
DBA-HA1W	「i」	2007~2008	13,812	
CBA-HA1W		2007~2008	5,587	
DBA-CS2A	「LANCER」	2007~2008	4,990	
DBE-CS2V		2007~2008	4,530	
DBA-CS2W		2007	235	
TA-CS5A		2007	21	
CBA-CS5AZ		2007~2008	1,126	
LA-CS5W		2007	309	
TA-CS5W		2007	31	
CBA-CS6A		2007	100	
GH-CT9A		2007	3	
		TOTAL	30,744	