

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2196	DATE	Jun. 18 2015
MANUFACTURER	Mercedes-Benz (Japanese importer : Mitsubishi Fuso Truck and Bus Corporation)		
DESCRIPTION OF DEFECT	On the rear car of some articulated buses, dew condensation water underneath the roof panel under the roof air conditioner unit may drop on the distribution panel. This may corrode and short-circuit the electrical circuit in the distribution panel, resulting in faulty illumination of some warning lamps or other troubles. In the worst case, fire may be caused.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unclear model	「Citaro-G」	2007~2010	21
TOTAL			21