

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-2182	DATE	Jun 4, 2015
MANUFACTURE	General Motors Company (Japanese Importer : General Motors Japan Ltd.)		
DESCRIPTION OF DEFECT	<p>General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2005-2013(*1) model year Chevrolet Corvette vehicles, when the engine is warm, the underhood bussed electrical center (UBEC) housing will expand, causing the headlamp low-beam relay control circuit routed wire to bend slightly. After the wire is repeatedly bent, it can fracture and separate. When this occurs, the low-beam headlamps will not illuminate. As the UBEC housing cools and contracts, the low-beam headlamp function may return. This condition does not affect the high-beam headlamps, marker lamps, turn signals, daytime running lamps or fog lamps. Loss of low beam headlamps when they are required could reduce the driver's visibility, increasing the risk of a crash.</p> <p>(*1) Safety Recall for the 2008-2013 model year Corvettes for only Japan.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
「GH-X245」 「ABA-X245S」 「-X245S-」	「Corvette」 / 「Corvette Z16」	2005 — 2013	803
「GH-X245」 「ABA-X245A」	「Corvette Z06」	2006 — 2012	223
「-X245A-」	「Corvette ZR1」	2010 — 2012	31
		TOTAL	1057