

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3623	DATE	July 31 ,2015
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	<p>On certain route buses with a glide slide door, there are some in which bracket which conducts the power of the air cylinder for door opening and closing and the spring pins which fixes the rotating axis making the door open and close are cracked. If the vehicle is continued to be used under the condition, in the worst case, both of the spring pins may break, resulting the door to open while driving or the switching operation of the door from the driver seat to be non-active.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PJ-LV234L1	[ERGA]	2004-2007	748
PDG-LV234L2		2007-2010	775
PKG-LV234L2		2010-2015	935
LDG-LV234L3			
LKG-LV234L3			
QDG-LV234L3			
QKG-LV234L3			
QPG-LV234L3			
QQG-LV234L3			
OSG-LV234L3			
PJ-LV234N1		2004-2007	298
PDG-LV234N2		2007-2010	366
PKG-LV234N2			
LDG-LV234N3		2010-2015	691
LKG-LV234N3			
QDG-LV234N3			
QKG-LV234N3			
QPG-LV234N3			
QQG-LV234N3			
KL-LV280L1			
KL-LV280N1	2000-2005	152	
KL-LV280Q1	2001	4	
KL-LV834L1	2000-2005	223	
KL-LV834N1	2000-2004	62	
KK-LR233J1	[ERGA MIO] [GALA MIO]	1999-2003	34
U-LV224K	[CUBIC]	1994	1
KC-LV280L		1995-2002	36
KC-LV280N		1995-2002	39

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KC-LV280Q	[CUBIC]	1994-2000	21
NE-LV288N		1997-1998	2
KC-LV380L		1995-2000	32
KC-LV380N		1995-2000	21
KC-LV380Q		1994-1999	13
KC-LV832L		1998-2000	53
KC-LV832N		1998-2000	36
KL-KV280L1		[HINO BLUE RIBBON II]	2004-2005
KL-KV280N1	2004		4
		TOTAL	5,260