

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3615	DATE	Jul 29, 2015
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to improper instruction for production of rear seat, the clearance of inner part of the latch which fixes rear seat on body might be narrow.</p> <p>Therefore, operation of lock release lever would become worse. In the worst case, rear seat could not be fixed securely.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
HBD-DA17V	EVERY	2015	350
EBD-DA17V			391
HBD-DR17V	NV100 CLIPPER		13
EBD-DR17V			5
HBD-DG17V	SCRUM		2
			TOTAL