

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2208	DATE	July 23,2015
MANUFACTURER	Mitsubishi Motors(Thailand)Co., Ltd.		
DESCRIPTION OF DEFECT	In the inflator for the driver side airbag, it is confirmed that there are some propellants with the great variability in density as a result of the investigation for the returned parts from the market by the other manufacturer. As a result, those inflators will be replaced with the new ones as a preventive measure since those airbags may not deploy properly although the cause has not been identified.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABF-KB9T	「TRITON」	2006~2010	1,396
		2006~2010	1,396