

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3610	DATE	July 15, 2015
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	<p>The investigation result by another automobile manufacturer shows that some inflators of driver airbags collected from the field have wide dispersion in the density of gas generating propellant.</p> <p>Though the cause of it has not been identified yet, it is possible that such airbags might not deploy properly.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-L235S	ESSE	2006-2011	145,041
CBA-L245S			16,140
DBA-L245S			
TA-L250S	Mira	2006-2007	15,903
LE-L250V			21,507
GBD-L250V			
TA-L260S			2,934
LE-L260V			2,562
LE-S320V	HIJET	2006-2010	59,230
GBD-S320V			
HAD-S320V			
LE-S330V			27,204
GBD-S330V			
LE-S320W	HIJET DECKVAN	2006-2007	707
LE-S330W			993
		TOTAL	292,221