

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import Vehicles~~

CAMPAIGN No.	GAI-2205	DATE	10/07/2015
MANUFACTURE	McLaren (Japanese Importer : McLaren Automotive ASIA Pte Ltd)		
DESCRIPTION OF DEFECT	There are a number of vehicles which may have the incorrect Loctite tread-lock used when fitting the electronic parking brake retention bolts, which may allow torque relaxation. There is a possibility this may result in the bolts becoming loose.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-MP4-12C	「McLaren MP4-12C」	2012-2013	65
ABA-MP4-12CS	「McLaren MP4-12C Spider」	2013	35
		TOTAL	100