

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3605	DATE	July.9. 2015
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	On investigation of the certain types of driver's SRS airbag inflators withdrawn from the market, it was found that some of them varied greatly in density of gas generating propellant. Although the cause is not determined yet, this can be an impediment to normal deployment of airbag, and therefore, the said inflators will be replaced with new ones by way of precautionary measures.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GD1	「FIT」	2007	61,344
DBA-GD2			7,238
DBA-GD3			5,937
DBA-GD4			858
DBA-GE6		2007~2011	508,431
DBA-GE7			38,371
DBA-GE8			84,165
DBA-GE9			7,081
DAA-GP1			2010~2011
CBA-JE2	「ZEST」	2007~2011	21,883
DBA-JE1	「ZEST」 「ZEST SPARK」		154,854
DBA-JE1 “kai”(modified)	「ZEST」		1,820
DBA-RN6	「STREAM」		114,448
DBA-RN7			10,217
DBA-RN8		22,125	
DBA-RN9		3040	
DAA-ZE2	「INSIGHT」	2008~2011	143,787

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
DAA-ZE3	「INSIGHT EXCLUSIVE」	2011	1,578	
DBA-RG1	「STEP WGN」	2007～2009	95,012	
DBA-RG2			14,631	
DBA-RG3	「STEP WGN SPADA」		5,446	
DBA-RG4			1,222	
DBA-GJ1	「AIRWAVE」	2007～2010	34,296	
DBA-GJ2			8,244	
DBA-RT1	「CROSSROAD」		11,897	
DBA-RT2			4,170	
DBA-RT3			10,337	
DBA-RT4			6,659	
DBA-RE3	「CR-V」		14,715	
DBA-RE4			16,450	
DAA-GP2	「FIT SHUTTLE」	2011	29,812	
DBA-GG7			6,745	
DBA-GG8			1,263	
DBA-GK1	「MOBILIO SPIKE」	2007～2008	20,056	
DBA-GK2			3,819	
DBA-GB1	「MOBILIO」		9,461	
DBA-GB2			1,376	
ABA-JD1	「THAT'S」	2007	18,780	
ABA-JD2			2,948	
DBE-GJ3	「PARTNER」	2007～2010	5,564	
DBE-GJ4			1,792	
		TOTAL	1,625,144	