

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3575	DATE	July, 7, 2015
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	Front tire (tire size 7-16) fixing bolts for the tractor equipped with front loader may be loosen due to in the early stage torque down. That leads to the crack of front tire wheel.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KTA	「KT20PC」	2002～2005	321
KTB	「KT24PC」	2002～2005	666
KTC	「KT27PC」	2002～2005	295
	「KT30J」	2002～2005	603
SA-KTD	「KT210PC」	2005～2007	229
SA-KTE	「KT230PC」	2005～2007	325
	「KT250PC」	2005～2007	625
SA-KTF	「KT280PC」	2005～2007	280
	「KT280J」	2005～2007	315
	「KT300」	2005～2007	230
	「T240DPC」	2006～2007	382
		TOTAL	4,271