

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 5 8 9	DATE	Jul.2.2015
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>Due to an inappropriate program of the engine control computer for the vehicles without idling-stop system, the engine torque will not be controlled while the Electronic Stability Control is operated. Therefore, although the vehicles are controlled by the brake force adjustment, the driving stability might not be enough.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-C26	SERENA	2013	4,032
DBA-NC26		~	1,550
DBA-SC26	SUZUKI LANDY	2015	361
DBA-SNC26			113
		TOTAL	6,056