

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3606	DATE	Jul.17 2015
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	As to the road working vehicles, it was found that the non-water proof type switches for the working devices were installed due to improper manufacturing process. Therefore, the working devices may be functioned unexpectedly during travelling due to short circuit at the switch terminals by penetration of rainwater, etc..		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
PDG-NKR85YN	—	2010	1	
TKG-XZU640F	—	2013	1	
TKG-NKR85N	—	2014	2	
LKG-FE7JJAA 改	—	2012	1	
TOTAL			5	