

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic, Import Vehicles

CAMPAIGN No.	GAI-2216	DATE	August 18, 2015
MANUFACTURE	ADIVA CO.,LTD (Japanese Importer : EKA CO.,LTD )		
DESCRIPTION OF DEFECT	Regarding the steering device, due to an error in the manufacturing process of the steering arm, the lock nut at the tie rod may loosen. Because of that, if the vehicle is used without rectification, the handle may loosen eventually. In worst case scenario, the steering arm may become bent, resulting in the malfunction of steering arm.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TD40 ADIVA	AD3	2013-2014	54 units
		TOTAL	54 units