

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	GAI-2177	DATE	18 August, 2015
MANUFACTURER	<p>MASERATI S.p.A. (Japanese Importer: Maserati Japan Ltd.)</p>		
DESCRIPTION OF DEFECT	<p>This update is necessary to fix unexpected EPB warning light on due to errors present in the EPB control unit. * NOTE; Due to this defect is against to Japanese safety regulation this campaign is submitted as Recall campaign nevertheless this campaign was treated as Service campaign in all other countries.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-MQP38A	「Quattroporte」	2013, 2014, 2015	271
ABA-MQP30AA		2013, 2014, 2015	89
ABA-MQP30A		2013, 2014, 2015	303
ABA-MG30AA	「Ghibli」	2013, 2014, 2015	197
ABA-MG30A		2013, 2014, 2015	624
ABA-MG30B		2014, 2015	479
		TOTAL	1,963