

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

| | | | |
|-----------------------|---|------|------------------|
| CAMPAIGN No. | Gai-2206 | DATE | October 29, 2015 |
| MANUFACTURE | Automobiles PEUGEOT (Japanese Importer : PEUGEOT CITROËN JAPON Co.,Ltd.) | | |
| DESCRIPTION OF DEFECT | <p>1. Because some bolts connecting the front subframe to the lower arm are inappropriate, the bolts may be broken and then noise may occur. If the bolts are continuously used, the lower arm will detach from the sub frame. If the worst happens, the steering wheel operation may be disturbed.</p> <p>2. Because a wrong part may be assembled as the harness support fixing the engine harness attached to the battery tray, it interferes the radiator lower hose, resulting in the damage of the lower hose. Thus, if used continuously as it is, the lower hose may be cracked, and the coolant may be leak. If the worst happens, the engine may be overheated.</p> | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|--------------|-------------------|---------------------|-------------------|
| ABA-T9HN02 | PEUGEOT 308 | 2014 | 554 |
| ABA-T9WHN02 | PEUGEOT 308 | 2014 | 327 |
| ABA-B785G01 | CITROEN C4Picasso | 2014 | 173 |
| ABA-B7875G01 | CITROEN C4Picasso | 2014 | 355 |
| | | TOTAL | 1409 |