

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2249	DATE	October 21 st 2015
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to premature aging of the material of the oil filter housing, the housing may become deformed and the sealing may become insufficient. As a result, a small amount of coolant or engine oil may leak from the seal, which conflicts with the Japanese safety regulation Article 8.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-3B20	「BMW 320i」	2012	5
DBA-3A20	「BMW 328i」	2011 - 2012	670
DBA-XG20	「BMW 523i」	2011 - 2012	1,730
DBA-XL20	「BMW 523i ツーリング [®] 」	2011 - 2012	537
DBA-XG28	「BMW 528i」	2011 - 2012	496
DBA-XL28	「BMW 528i ツーリング [®] 」	2011 - 2012	114
DBA-FR35	「BMW 535i」	2011	1
DAA-FZ35	「BMW ActiveHybrid 5」	2011	51
DBA-VM20	「BMW X1 xDrive 20i」	2011	842
	「BMW X1 xDrive 28i」	2011	463
DBA-WX20	「BMW X3 xDrive 20i」	2011 - 2012	34
DBA-LL20	「BMW Z4 sDrive 20i」	2011 - 2012	307
TOTAL			5,250