

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

 Domestic/Import Vehicles

CAMPAIGN No.	3662	DATE	Oct.21.2015
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	<p>(1)In the DPR (Diesel Particulate Active Reduction system) of the subject vehicles, due to improper seal structure at the electrical fuel cutoff valve, there is a possibility that water could intrude from the contact surface between the waterproof cap and the cutoff valve body. If this occurs, the coil wire in the cutoff valve could have a short-circuit or disconnection and the warning light illuminates, causing the resin component to have a damage by heat generation at the coil, in the worst case, resulting in fuel leakage from the cutoff valve.</p> <p>(2)In the automatic clutch unit of the mechanical automatic transmission,</p> <p>①due to improper routing of the electric wire harness connected to the operational motor, there is a possibility that the waterproof grommet could become deformed causing the water to intrude into the motor. If this occurs, the motor brush could not move smoothly and the warning light illuminates. In the worst case, the motor could seize and the clutch may not operate, resulting in the vehicle becoming inoperative.</p> <p>②due to improper routing of the lead wire connected to the motor brush in the motor, there is a possibility that the lead wire could catch on the guide. If this occurs, the motor brush could not move smoothly leading to conduction failure. In the worst case, the motor could not operate, resulting in the vehicle becoming inoperative.</p> <p>③due to the inadequate control program, if the vehicle is frequently started and stopped, the brush of the operational motor could wear prematurely.</p> <p>(3) In the passenger side manual adjusted outer rearview mirror assembly of the route van, due to the improper fixing method between mirror and the mirror assembly body, there is a possibility that the claw fixing the mirror to the body could wear by vibration while driving and eventually may break. In the worst case, the mirror could be detached and the driver cannot confirm rearward traffic conditions.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SJG-XKC605M TQG-XKC605M TSG-XKC605M	[HINO Dutro]	2011～2015	383
SJG-XKC645M TQG-XKC645M TSG-XKC645M		2011～2015	89
SJG-XKC655M TQG-XKC655M TSG-XKC655M		2011～2015	51

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SJG-XKU600M SJG-XKU600X TQG-XKU600M TQG-XKU600X TSG-XKU600M TSG-XKU600X	[HINO Dutro]	2011～2015	621
SJG-XKU605M TQG-XKU605M TSG-XKU605M		2011～2015	235
SJG-XKU640M TQG-XKU640M TSG-XKU640M		2011～2015	53
SJG-XKU645M TQG-XKU645M TSG-XKU645M		2011～2015	48
SJG-XKU650M TQG-XKU650M TSG-XKU650M		2011～2015	164
SJG-XKU655M TQG-XKU655M TSG-XKU655M		2011～2015	131
SJG-XKU700M TQG-XKU700M TSG-XKU700M		2011～2015	104
SJG-XKU710M TQG-XKU710M TSG-XKU710M		2011～2015	1,306
SJG-XKU720M SJG-XKU720MKAI TQG-XKU720M TQG-XKU720MKAI TSG-XKU720M		2011～2015	364
SKG-XZC600M TKG-XZC600M		2011～2014	1,173
SKG-XZC605M SKG-XZC605Y TKG-XZC605M TKG-XZC605Y		2011～2015	2,975
SKG-XZC610T TKG-XZC610T		2011～2014	2,517
SKG-XZC630T TKG-XZC630T		2011～2014	359
SKG-XZC645M TKG-XZC645M		2011～2014	936
SKG-XZC655M TKG-XZC655M		2011～2014	861
SKG-XZC675M SKG-XZC675T TKG-XZC675M TKG-XZC675T		2011～2014	402

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-XZC710M TKG-XZC710M	[HINO Dutro]	2011～2014	717
SKG-XZU600E SKG-XZU600EKAI SKG-XZU600F SKG-XZU600M SKG-XZU600T SKG-XZU600X SKG-XZU600XKAI TKG-XZU600E TKG-XZU600EKAI TKG-XZU600F TKG-XZU600FKAI TKG-XZU600M TKG-XZU600T TKG-XZU600X TKG-XZU600XKAI		2011～2014	5,923
SKG-XZU605M TKG-XZU605M		2011～2014	3,236
SKG-XZU610T TKG-XZU610T		2011～2014	802
SKG-XZU620T TKG-XZU620T		2011～2014	4,045
SKG-XZU630T TKG-XZU630T		2011～2014	982
SKG-XZU640F SKG-XZU640M TKG-XZU640F TKG-XZU640M		2011～2014	1,886
SKG-XZU645M TKG-XZU645M		2011～2014	421
SKG-XZU650F SKG-XZU650M TKG-XZU650F TKG-XZU650M TKG-XZU650MKAI		2011～2014	3,207
SKG-XZU655M SKG-XZU655MKAI TKG-XZU655M TKG-XZU655MKAI		2011～2014	943
SKG-XZU675M SKG-XZU675T TKG-XZU675M TKG-XZU675T		2011～2014	1,801
SKG-XZU685M TKG-XZU685M		2011～2014	1,777
SKG-XZU695M TKG-XZU695M		2011～2014	537

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SDG-XZU700M SDG-XZU700MKAI SDG-XZU700X SKG-XZU700M TKG-XZU700M TKG-XZU700MKAI TKG-XZU700X	[HINO Dutro]	2011～2014	2,253
SDG-XZU710M SDG-XZU710MKAI SKG-XZU710M SKG-XZU710MKAI TDG-XZU710M TDG-XZU710MKAI TKG-XZU710M TKG-XZU710MKAI		2011～2014	6,686
SDG-XZU720M SDG-XZU720MKAI SKG-XZU720M TDG-XZU720M TDG-XZU720MKAI TKG-XZU720M TKG-XZU720MKAI		2011～2014	3,798
SDG-XZU730M TDG-XZU730M TKG-XZU730M		2011～2014	427
SKG-XZU775M TKG-XZU775M TKG-XZU775MKAI		2011～2014	360
SJG-XKC605 TQG-XKC605 TSG-XKC605	[Toyota Dyna200] [Toyota ToyoaceG25] [Toyota Dyna300]	2011～2015	327
SJG-XKC655 TQG-XKC655 TSG-XKC655	[Toyota ToyoaceG35] [Toyota Dyna400] [Toyota ToyoaceG45]	2011～2015	9
SJG-XKU600 SJG-XKU600A TQG-XKU600 TQG-XKU600A TSG-XKU600		2011～2015	34
SJG-XKU605 TQG-XKU605 TSG-XKU605		2011～2015	87
SJG-XKU640 TSG-XKU640		2011～2015	3
SJG-XKU645		2011	1
SJG-XKU650 TQG-XKU650 TSG-XKU650		2011～2015	33
SJG-XKU655 TQG-XKU655 TSG-XKU655		2011～2015	30

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SJG-XKU700 TQG-XKU700 TSG-XKU700	[Toyota Dyna200] [Toyota ToyoaceG25] [Toyota Dyna300]	2011～2015	12
SJG-XKU710 TQG-XKU710 TSG-XKU710	[Toyota ToyoaceG35] [Toyota Dyna400] [Toyota ToyoaceG45]	2011～2015	123
SJG-XKU720 TQG-XKU720 TSG-XKU720		2011～2014	21
SKG-XZC600 TKG-XZC600		2011～2014	2,292
SKG-XZC605 SKG-XZC605V TKG-XZC605 TKG-XZC605V		2011～2015	4,056
SKG-XZC610D TKG-XZC610D		2011～2014	500
SKG-XZC630D TKG-XZC630D		2011～2014	144
SKG-XZC645 TKG-XZC645		2011～2014	572
SKG-XZC655 TKG-XZC655		2011～2014	221
SKG-XZC675 TKG-XZC675 TKG-XZC675D		2011～2014	405
SKG-XZC710 TKG-XZC710		2011～2014	198
SKG-XZU600 SKG-XZU600A SKG-XZU600D SKG-XZU600H SKG-XZU600W TKG-XZU600 TKG-XZU600A TKG-XZU600D TKG-XZU600H TKG-XZU600W		2011～2014	955
SKG-XZU605 TKG-XZU605		2011～2014	3,141
SKG-XZU610D TKG-XZU610D		2011～2014	169
SKG-XZU620D TKG-XZU620D		2011～2014	922
SKG-XZU630D TKG-XZU630D		2011～2014	149
SKG-XZU640 SKG-XZU640W TKG-XZU640 TKG-XZU640W		2011～2014	405

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-XZU645 TKG-XZU645	[Toyota Dyna200] [Toyota ToyoaceG25]	2011～2014	409
SKG-XZU650 TKG-XZU650 TKG-XZU650W	[Toyota Dyna300] [Toyota ToyoaceG35] [Toyota Dyna400]	2011～2014	1,257
SKG-XZU655 TKG-XZU655	[Toyota ToyoaceG45]	2011～2014	1,033
SKG-XZU675 SKG-XZU675D TKG-XZU675 TKG-XZU675D		2011～2014	1,153
SKG-XZU685 TKG-XZU685		2011～2014	764
SKG-XZU695 TKG-XZU695		2011～2014	483
SDG-XZU700 SDG-XZU700A SKG-XZU700 TKG-XZU700 TKG-XZU700A		2011～2014	303
SDG-XZU710 SKG-XZU710 TDG-XZU710 TKG-XZU710		2011～2014	2,651
SDG-XZU720 SKG-XZU720 TDG-XZU720 TKG-XZU720		2011～2014	2,163
SDG-XZU730 TDG-XZU730 TKG-XZU730		2011～2014	174
SKG-XZU775 TKG-XZU775		2011～2014	277
TOTAL			78,049