

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	2248	DATE	Oct 16,2015
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	<p>The ozone resistance of fuel hoses on the crane carrier device purposed to prevent carbon monoxide emissions, the DPF (Diesel particulate filter) is not adequate.</p> <p>This situation initially results in early hose deterioration and cracking followed by fuel leaking, and an inability to supply fuel to the DFP and ultimately an inability to combust the accumulated soot.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
FAUN	RTF600-7	2011 — 2015	23
		TOTAL	23