

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-2238	DATE	Oct 15, 2015
MANUFACTURE	General Motors Company (Japanese Importer : General Motors Japan Ltd.)		
DESCRIPTION OF DEFECT	General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2013-2016 model year ATS sedan vehicles. These vehicles have a coil antenna module that powers the rear defogger system located in the driver side rear pillar. In certain of these vehicles, the coil antenna module may generate significant temperatures if the module is subjected to excessive cycling or continuous operation and the module was manufactured with critically weak terminal connectivity. Where this condition exists, a fire may develop inside the rear pillar on the driver's side of the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
「ABA-A1SL」	「ATS」	2013 - 2015	550
		TOTAL	550