

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-2240	DATE	Oct 15, 2015
MANUFACTURE	General Motors Korea Company (Japanese Importer : General Motors Japan Ltd. )		
DESCRIPTION OF DEFECT	It is reported that some of these vehicles' fuel pump flow control module were built with contamination. This contamination may cause an electrical short in the module. In the event that the module experiences an electrical short, the vehicle may display a check engine light, fail to start or stall.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
「Unknown」	「Captive」	2013	22
		TOTAL	22