

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2247	DATE	October. 15. 2015
MANUFACTURER	HONDA CANADA INC.		
DESCRIPTION OF DEFECT	With regard to airbag control units, some may lack electrical noise immunity. Because of the noise emitted by electrical equipment of vehicle, IC chips in such a unit can be damaged whilst in use and the airbag could, when things are at the worst, be thereby deployed unexpectedly while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UA-YD1	MDX	2003	1,016
		TOTAL	1,016