

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2231	DATE	Oct 9, 2015
MANUFACTURE	Harley-Davidson Motor Company (Japanese Importer : Harley-Davidson Japan K.K.)		
DESCRIPTION OF DEFECT	A poor seal may allow an interruption to the fuel supply under acceleration at low fuel levels, possibly before the low fuel indicator has illuminated. If this condition remains undetected, under acceleration with the fuel level below 0.8 gallons, the motorcycle may briefly hesitate and then restore power abruptly, possibly leading to a loss of control.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-XGB	STREET 750	2015	730
BBC	STREET 750	2015	3
		TOTAL	733