

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3649	DATE	October 8, 2015
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	Due to inappropriate control program of the system, that calls the attention of following vehicles by the emergency flashing signal at sudden braking and/or the accident, the frequency of the emergency flashing signal doesn't meet the safety standard when the system is operating.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GJEFP	Mazda 「ATENZA」	2014-2015	612
DBA-GJEFW		2014-2015	512
DBA-GJ5FP		2014-2015	589
DBA-GJ5FW		2014-2015	451
LDA-GJ2AP		2014-2015	757
LDA-GJ2FP		2014-2015	2,470
LDA-GJ2AW		2014-2015	1,310
LDA-GJ2FW		2014-2015	2,682
DBA-KEEFW	Mazda 「CX-5」	2014-2015	2,157
DBA-KE5AW		2014-2015	773
DBA-KE5FW		2014-2015	568
LDA-KE2AW		2014-2015	7,232
LDA-KE2FW		2014-2015	9,186
DBA-BM5AP	Mazda 「AXELA」	2015	313
DBA-BM5FP		2015	2,654
DBA-BM5AS		2015	516
DBA-BM5FS		2015	4,754
DBA-BMEFS		2015	1,912
LDA-BM2FS		2015	1,388
		Total	40,836