

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2244	DATE	October.1. 2015
MANUFACTURER	HONDA AUTOMOBILE (THAILAND) CO., LTD.		
DESCRIPTION OF DEFECT	On investigation of the certain types of driver's SRS airbag inflators withdrawn from the market, it was found that some of them varied greatly in density of gas generating propellant. Although the cause is not determined yet, this can be an impediment to normal deployment of airbag, and therefore, the said inflators will be replaced with new ones by way of precautionary measures.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GD8	「FIT ARIA」	2007	342
DBA-GD9			96
		TOTAL	438