

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	3628	Date	Nov., 27, 2015
Manufacture	CATERPILLAR JAPAN LTD.		
Description of Deffect	A governor cable may be fractured by un-intended bending due to an interference between cable crimping and linkage plate. Then, the vehicle may be stuck.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-W4T	「901C」	2013, 2014	693
		TOTAL	693