

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3670	DATE	November 18, 2015
MANUFACTURER	AICHI Corporation		
DESCRIPTION OF DEFECT	<p>Battery power unit on vehicle mounted type elevation work platform fails to charge vehicle's battery.                  The battery charge control circuit in the battery power unit for vehicle's battery occasionally generates electric noise immediately after stopping charge for vehicle's battery because of inappropriate design.                  This noise damages IC in the circuit, therefore it disables to charge the vehicle's battery.                  Keeps using the machine in this condition results in failure to start engine after work</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-NKR85YN	ELF	2014	19
TKG-XZU600F	HINO DUTRO	2014	6
TKG-XZU600W	DYNA / TOYOACE	2014	2
TOTAL			27