

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai -2254	DATE	10 November, 2015
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	There is a possibility that the fuel low-pressure line can start to leak near the connection point to the distributor pipe on the affected vehicles. As a result, fuel will leak out at the connection point. If this happens, the customer may get a smell of fuel.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-95BCTM	Macan S	2015	695
		2016	198
ABA-95BCTMA		2015	103
		2016	20
DBA-95BCTL	Macan Turbo	2015	234
		2016	85
DBA-95BCTLA		2015	284
		2016	73
		TOTAL	1692