

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	3729	DATE	December 25, 2015
MANUFACTURER	SUMITOMO NACCO MATERIALS HANDLING CO., LTD. (Japan)		
DESCRIPTION OF DEFECT	There is that bubbles are generated in the fuel line. It may accumulate air bond bubbles together while the engine is stopped. The engine may stop, when the air enters into the engine immediately just after the truck is restarted.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-D2N	FD25PXIII	2015	1
YDN-D3K	FD35PXIII	2015	1
YDN-SD2G	FD20PXIII FD25PXIII	2015	2
SD3B	FD30PXIII	2015	2
		TOTAL	6